



Outline the Scene	Incident	240v Power Cable Cut with Power Saw
	Subject	Safe work around live services
	Critical Risk Type	CR037 Contact with Electricity
	Incident Date	31/05/2023
	Business Unit	Brian Perry Civil – Southern Region
What happened?		vorkers were undertaking work outside of a Wellington
	 Water Limited, Wastewa The work was being under was offline, and locked o 	rtaken during a planned shutdown and the pump station
		te to expose the existing services so the repair work
	 An existing 150mm diam section to be installed 	eter waste pipe had to be cut out to allow for a new
	 A worker used a power consisting pipe 	ut off saw fitted with an abrasive disc to cut through the
	 As the cut was completed 240v electrical cable white 	I, the worker lifted the saw, the abrasive disc contacted a ch was near the pipe
		ediately aware that the cable had been damaged, shortly e cable started to spark and crackle.
	 The work area was imme (WEL) were notified of th 	diately evacuated, and Wellington Electricity Limited e incident
		on site to assess and repair the damaged cable



In the second

DATE OF RELEASE 1/06/2023

R. Mar T.

120





	Have all services been positively identified and exposed?
	• Are controls in place to protect existing services from the task?
	• Can utility services be isolated at source by the utility providers?
	• Are workers aware of the risks associated with work around the existing services?
	• Have we considered alternative methods of cutting that reduce risk to existing services?
	 Does the project emergency management plan include details for the utility's companies?

Adam Hunt – Regional HSE Manager adamh@fcc.co.nz 027 567 5814

