

26 January 2024



Tēnā koe

# Official information request for reports done on your property and surrounding properties for the past five years

Thank you for your official information requests dated 1 December 2023 and 6 December 2023 as follows:

#### Request dated 1 December 2023

forward all reports done on my property at 48 Kanpur Road, Broadmeadows, Wellington regarding our water problems, both any carried out this year and in previous years. There was also one carried out 5-6 (?) years ago which I also never received a copy of.

#### Request dated 6 December 2023

I request all other reports done on this property and surrounding properties over the past five years: CTV coverage, dye tests, and all tests carried out on branch pipes, not just the main pipes and water overflow pipes etc. - these are required for an Independent Review investigation.

We have considered your request in accordance with the Local Government Official Information and Meetings Act 1987 (the Act) and determined that we are able to grant your request in full.

In response to your request please find enclosed the following documents:

- 1. Service Request Data
- 2. Water Sample Results dated 28 November 2023
- 3. The CCTV footage and map of the storm water network are provided to you in the <u>Drop Box Folder</u>.

Some information within these documents has been redacted under section 7(2)(a) of the Act to protect the privacy of natural persons.

Please refer to the email from Wellington Water dated 4 December 2023 regarding the outcome of the water seepage investigations.

For the latest news and updates, follow us on our social channels:

(f) /wellingtonwater (y) @wgtnwaternz & @wgtnwateroutage

www.wellingtonwater.co.nz

@wellington\_water

### Our water, our future.

Wellington Water is owned by the Hutt, Porirua, Upper Hutt and Wellington City Councils, South Wairarapa District Council and Greater Wellington Regional Council. We manage their drinking water, wastewater and stormwater services.



You have the right to seek an investigation and review by the Ombudsman of this decision. Information about how to make a complaint is available at <u>www.ombudsman.parliament.nz</u> or freephone 0800 802 602.

If you would like to discuss this reply with Wellington Water, please contact the Business Services team by email to official.information@wellingtonwater.co.nz

Nāku noa, nā



**Group Manager Customer Operations** 

For the latest news and updates, follow us on our social channels:

f /wellingtonwater

(S) @wgtnwaternz & @wgtnwateroutage

@ @wellington\_water

#### www.wellingtonwater.co.nz

Wellington Water is owned by the Hutt, Porirua, Upper Hutt and Wellington City Councils, South Wairarapa District Council and Greater Wellington Regional Council. We manage their drinking water, wastewater and stormwater service

### Our water, our future.



# Service Request Data – OIA IRO-542 Job Sheet

	C				i i			Descention	Convertextion (Closed		WAY - STORE STORE		A data and take states
	Council Reference ID	Accet ID	Work Order Summany	Job Dotails	Mator	Driority	Status	Reported	Completion/Closed	Entry Data	Work Log		Additional Job Notes
Address 50 Kanpur Road, Broadmeadows, Wellington, 6035	Reference ID WCCSR-364877	Asset ID WCC_SWP010052	Vork Order Summary Public Info Request 50 Kanpur Road, Broadmeadows	Job Details <div>I am emailing \$ 7(2)(a) They have had major issues with water previously gushing through their house. We would like to establish where this water is coming from. As you can imagine with mold and dampness it is not conducive to a healthy environment \$ 7(2) 8 7(2)(a) Below is a link that I was able to source for water lines. The address is 50 Kanpur Road, Broadmeadows, Johnsonville, We lington. https://wellingtonwater.maps.arcgis.com/a pps/webappviewer/index.html?id=205552 a0ffab4c20ae375fab08c6cb9f 7 7 7 2 7 7 7 8 7 8 7 8 7 8 7 8 7 8 7 8</div>	Water Stormwater	4	CLOSE	Date 4/20/2022 7:16:30 AM	Bite B/22/2022 8:46:19 AM	Entry Date 4/20/2022 7:16:45 AM	Summary Note from Council	We keep to be the set of	



•	Council							Reported	Completion/Closed		Work Log		Additional Job Notes
Address	Reference ID	Asset ID	Work Order Summary	Job Details	Water	Priority	Status	Date	Date	Entry Date	Summary	White Log Detail	
Address		Asset ID				vernin		iall	ormationan		SACT	In the assessment we would	
						Nermi				4/22/2022 3:37:45 PM	Assigned to	Assigned to T/L *//// RICH TEXT>	
					ocal Ge					5/4/2022 10:17:35 AM	Note from Council	Kia Ora, I had emailed a few weeks ago. Could you please let us know where we are at in the queue.	
				the the								Kind regards s 7(2)(a)	
				dei						7/19/2022 10:39:03 AM	Assigned to CCTV	Please camera storm water network, see attachment. <br RICH TEXT>	
				dul.						7/26/2022 7:49:27 AM	Status Change to PAUSE	Team lead to review footage	
				eleased under the						7/26/2022 3:45:27 PM	Status Change to PAUSE	Team lead to review footage	
				2010						7/27/2022 8:05:27 AM	Status Change to PAUSE	Pause	



	Council			19				Reported	Completion/Closed		WorkLog		Additional Job Notes
Address		Asset ID	Work Order Summary	Job Details	Water	Priority	Status	<ul> <li>A state of the sta</li></ul>		Entry Date	Summary	Over Log Detail	Additional Job Notes
Address	Council Reference ID	Asset ID	Work Order Summary	Job Details	Water	.01	Status		mationari	8722022 9:45:36 AM	Work Log Summary CCTV Notes Udate	With Log Detail           27707/22 CCTV drain section SW013428 to SW006022 to SW013503 .TV: 3184:70,71 & amp; 72. Drain is OK. RICH TEXT            CCTV showed no faults, most likely ground water or issues with private drainage above property. EMailed customer to contact drain layer. RICH TEXT Hi,           My father responded to an earlier email but had no further contact from Wellington City Council. I have forwarded him this email.           If someone can be in contact with first it will be greatly appreciated.           Ng? mihi nui           7(2)(3)           Hello Info           This issue has not been resolved!!           I replied to an earlier email asking for the location of this flow and I did not get a reply! I had answered that the flow is at the back of the house from under the house.           We would like to locate the source and resolve it. I am wondering whether there is a leak in the waste	Additional Job Notes
	WO-357102	No Asset Selected	Drainage - 50 Kanpur Road, Broadmeadows	<div>Customer reports stonwater seeing onto properties at 50 and ve Kanpur Road they believe is emanating from the new construction at 55 Kanpur.</div> <dv>Customer advises that water is pond to under the house at 50</dv>	ocal G	3	PRECLAI	8/23/2023 9:00:46 AM	11/15/2023 4:04:03 PM	8/23/2023 9:10:04 AM	Added complaint to job - Assigned to TA	there is a leak in the waste water system above the property. Please call me on 57(2)(a) Kind regards 57(2)(a) > Talked to TA who attended in 2022. He will investigate further. Advised and customer. <br RICH TEXT>	
				and accumulating in pools at 48. raised to councillor Chung. RICHTEXT>						10/3/2023 1:31:19 PM	WCC Elected Member Support Advisor called	WCC Elected Member Support Advisor (2)(3) called wanting to follow up on this job. This is due to many complaints and escalations they are receiving for this matter. Advised how Customer Hub	



									Provide the Patrice of the				Weblink contract and one of
	Council			1.1.8.1.N				Reported	Completion/Closed		Work Log	W Log Detail	Additional Job Note
ress	Reference ID	Asset ID	Work Order Summary	Job Details	Water	Priority	Status	Date	Date	Entry Date	Summary	with Log Detail is unable to assist them	
												directly further, as their	
												queries and follow up	
												requests must be dealt	
												directly with the Resolutions	
											~	Team. Transferred call to	
											$\mathbf{O}$	Reso TL \$7(2)(a) to assist them further. RICH TEXT</td <td></td>	
										× N	• •	>	
										10/31/2023 1:01::27M	Assign to	<div<sup>s 7(2)(a) - Sample seepage</div<sup>	
										1:01:12 PM	s 7(2)(a)	coming from house, as well	
												as plan dye test for the curb and	
												channel. <div> </div> <	
										$\mathbf{P}$		div>III give you details on	
										•		where to dye and were to	
												sample. RICH</td <td></td>	
									annation an	12/4/2023	Update	TEXT> <div>Investigations that have</div>	
									×	8:19:18 AM	opuate	happened so	
												far: <div> </div> <p< td=""><td></td></p<>	
												class="MsoNormal">First	
												Job sent from TA straight to	
												North Drainage <o:p></o:p>	
								ficialIn				Drainage so.p. sto.p. stop	
												<ul><li><ul type="disc"></ul></li></ul>	
								$\cdot \alpha$				<li <="" class="MsoNormal" td=""><td></td></li>	
												style="mso-margin-top-	
							e e					alt:auto;mso-margin-bottom- alt:auto;	
												mso-list:l3 level1 lfo1;tab-	
												stops:list 36.0pt;list-style-	
							ont					type:"-	
												"">Stormwater and	
												Wastewater mains due tested and	
							•					flushed. <o:p></o:p>	
												<li>li class="MsoNormal"</li>	
												style="mso-margin-top-	
												alt:auto;mso-margin-bottom-	
												alt:auto; mso-list:l3 level1 lfo1;tab-	
					()	T						stops:list 36.0pt;list-style-	
												type:"- "">No dye	
												apparent in	
												seepage, no blockages,	
												mains operating as	
					$\mathbf{V}$							intended. <ul type="disc"&gt;</ul 	
				×									
												Leak	
				Released under the			1					Detection <o:p></o:p>	
							1					<ul type="disc"></ul>	
							1					<li><li>li class="MsoNormal"</li></li>	
							1					style="mso-margin-top-	
				<b>6</b>			1					alt:auto;mso-margin-bottom-	
							1					alt:auto;	
							1					mso-list:11 level1 lfo3;tab-	
												stops:list 36.0pt;list-style- type:"- "">No	
							1					leaks or sound	
				20°			1					identified above the	
				<b>√</b> − <sup>−</sup>					1			affected	
	1	1	•									resident. <o:p></o:p>	




	C			*				Destanting	version and the former of		Ver see la provinci		
Address	Council Reference ID	Asset ID	Work Order Summary	Job Details	Water	Priority	Status	Reported Date	Completion/Closed Date	Entry Date	Work Log Summary	Over Log Detail	Additional Job Notes
					Cal		ento			Neetil	SACT	<pre></pre> <pre></pre> <pre></pre> <pre>/ Class="MsoNormal" </pre> <pre>style="mso-margin-top- alt:auto;mso-margin-bottom- alt:auto;mso-list:11 level1 lfo3;tab- </pre> <pre>stops:list 36.0pt;list-style- </pre> <pre>type:"- ""&gt; noted that there     is groundwater coming off the bank at 69 Kanpur and disappearing through     the curb and channel.&lt;<o:p></o:p> </pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre>/ Class="MsoNormal"&gt;TA Investigations<o:p></o:p></pre> <pre>/ Investigations&lt;<o:p></o:p> <pre>&gt; <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre></pre> <pre>/ Class="MsoNormal"</pre> <pre>Style="mso-margin-top- alt:auto;mso-margin-top- alt:auto;mso-margin-bottom- alt:auto;     mso-list:10 level1 lfo4;tab- </pre> <pre>stops:list 36.0pt;list-style- </pre> <pre>type:"- ""&gt;Sample taken from 50     Kanpur, fluoride showed up at 0.2, tap level came back as 0.8.&lt;<o:p></o:p></pre> <pre></pre> <pre>/ Class="MsoNormal"</pre> <pre>style="mso-margin-top- alt:auto;mso-margin-top- alt:auto;</pre></pre></pre>	
48 Kanpur Road, Broadmeadows, Wellington, 6035	WCCSR-114143	WCC_WW019995	Fault 48 KANPUR ROAD, Broadmeadows	waste water pipe 48 Kanpur Rd, Broadmeadows for the last 2-4 years water (summer and winter) has leaked from the bank on and behind 48 Kanpur Road, Brotanieadows. Suspect it is a leak in the (a)te water pipe which runs down the coundary of 46 and 48 Kanpur from higher up Kanpur. Water is flooding the rear of 48 Kanpur and attempts are now trying to pipe this. Suspect the waste water pipe is leaking	Wastewater	3	CLOSE	3/2/2021 12:41:14 AM	3/11/2021 1:37:54 PM	3/2/2021 12:42:20 AM	Note from Council	Address: 48 KANPUR ROAD, Broadmeadows Open in Google Maps: https://www.google.com/map s/search/?api=1&query=- 41.23739454923562,174.79 21491964731	Customer concern that water has been coming out of the bank at the back of house for sometime now where the problem area is is long way from council asset but cctv both WW SW line and seen no issue explain to customer said it's only ground water



### Service Request Data - OIA IRO-542 Job Sheet

665	Council	Sector Sector						Reported	Complet
Address	Council Reference ID	Asset ID	Work Order Summary	Job Details into the properties of 46 and 48 and 50 Kanpur. URGENT attention required please. This has been bought to the attention of the council numerous times by residents and now is the time to action this. My home.	Water	Priority	Status	Reported Date	Complet Date
								ficial In	orma
					cal Gr		erit		
				Released under the					





Address	Council Reference ID	Asset ID		Job Dotaile	Watar	Deiovity	Status	Reported	Completion/Closed	Entry Doto	Work Log	Wyrk Log Detail	Additional Job Notes
Address	Reference ID	Asset ID	Work Order Summary	Job Details	Water		Status	Date	Date		Summary	befind 48 Kanpur Road, Broadmeadows. Suspect it is a leak in the waste water pipe which runs down the boundary of 46 and 48 Kanpur from higher up Kanpur. Water is flooding the rear of 48 Kanpur and attempts are now trying to pipe this. Suspect the wastewater pipe is leaking into the properties of 46 and 48 and 50 Kanpur. URGENT attention required please. Other comments: This has been bought to the attention of the council numerous times by residents and now is the time to action this. My home.	(d) A strange of an above approximate and the strange of the st
					6	Ner				3/2/2021 12:37:18 PM 3/5/2021	Note from Council Assigned to	WWL <sup>77999</sup> ) this has been moved from a P4 to a P2 due to nature of complaint. Assigned to <mark>97(2)(3)</mark> to	
					cal					3/5/2021 12:30:31 PM 3/9/2021	s 7(2)(a) <sub>to</sub> assess s 7(2)(a)	assess RICH TEXT	
				Q1						4:29:20 PM 3/12/2021	called for update. Note from	escalating to crew for notes. RICH TEXT Thank you for your quick	
				Released under the						8:00:32 PM	Council	Thank you for your quick professional service. Could I please request a written report as to the result and outcome of your investigation? Many thanks S 7(2)(a)	



Page 1 of 2 AR-23-NW-063394-01

## Food & Water Testing

**ANALYTICAL REPORT** 

REPORT CODE	AR-23-NW-063394-01	REPORT DATE 28/11/2023	
AttentionWellington WaS 7(2)(a)Wellington WaLevel 4, Ibm H25 Victoria StrPetone Lower	ater Management louse reet	os pet nos	
NEW ZEALAN	1D		
Email S / (2)(a)	@wellingtonwater.co.nz	Copy to: 57(2)(a) @wellingtonwater.co.nz), Wellington Water Ltd (drainageinvestigations@wellingtonwater.co.nz) 57(2)(a)	
Contact for your orders: Contract:	<mark>s 7(2)(a)</mark> Seepages PCC	Order code: EUNZWE-00152455	
		Purchase Order Number: 280881	
SAMPLE CODE	812-2023-00156333		
Sample described as: Reception Date & Time: Analysis Start Date & Time Sampled Date & Time	13/11/2023 16:05	adows, COG WO# 357102, <b>5</b> 7(2)(a) Analysis Ending Date: 28/11/2023 Sampler(s) <b>5</b> 7(2)(a)	
	RESULTS	LOQ	
NW007 Chloride Chloride (Cl)	16.4 mg/l	0.02	
ZM2H3 Enumeration of F Faecal Coliforms	aecal Coliforms By Membrane Filtra <100 cfu/100 m		
NW006 Fluoride Fluoride	0.23 mg/	0.02	
NW008 Nitrite-N Nitrite Nitrogen as N	<0.01	0.01	
SAMPLE CODE	812-2023-00156334		
Sample described as: Reception Date & Time: Analysis Start Date & Time	Tap - 50 Kanpur Rd Broadmeadows 13/11/2023 16:05 0:12/11/2023 16:45	s, COG WO# 357102, <mark>S 7(2)(a)</mark> Analysis Ending Date: 23/11/2023	
Sampled Date & Time	13/11/2023 10:00	Sampler(s) S7(2)(a)	
	RESULTS	LOQ	
NW006 Fluoride Fluoride	0.79 mg/l	0.02	
. )			
NW006 Fluoride: APHA Onlir	າe Edition 4110 B	NW007 Chloride: APHA Online Edition 4110 B	
NW008 Nitrite-N: APHA Onlir	ie Edition 4110 B	ZM2H3 Faecal Coliforms E (Water) [NZ] <100 >60 000 /100 ml (0-1) m-FC Agar-F: SMEWW 9222D; APHA 24th Edition	
2-0°	Signatu	ıre	




aluha



#### Food & Water Testing







Laboratory Supervisor Microbiology

Not Detected means not detected at or above the Limit of

X (Unsatisfactory) means does not meet the specification

✓ (Satisfactory) means meets the specification

LOQ means Limit of Quantification and the unit of LOQ is the same as

N/A means Not Applicable

Quantification (LOQ)

the result unit

**Testing Chemistry** 

**EXPLANATORY NOTE** 

Test is not accredited

- ② Test is subcontracted within Eurofins group and is accredited
- 3 Test is subcontracted within Eurofins group and is not accredited

Test is subcontracted outside Eurofins group and is accredited

S Test is subcontracted outside Eurofins group and is not accredited

© Test result is provided by the customer and is not accredited

- Tested at the sampling point by Eurofins and is not accredited
- <sup>®</sup> Tested at the sampling point by Eurofins and is accredited

Test is RLP accredited

Test is subcontracted within Eurofins group and is RLP accredited

The Customer acknowledges and accepts that: (a) where Eurofins is not responsible for sampling, the test result(s) in this report apply only to the sample as received. Customer is solely responsible for the sampling process and warrants that the sample provided to Eurofins is representative of the lot / batch from which the samples were drawn; and (b) Eurofins expresses no opinion and accepts no liability in respect of the Customer's production process or homogeneity of the product. This document can only be reproduced in full.

The tests are identified by a five-digit code, their description is available on request.

Accreditation does not apply to comments or graphical representations.

Unless otherwise stated, all tests in this analytical report (except for subcontracted tests) are performed at 85 Port Road, Seaview, Lower Hutt, Wellington, NEW ZEALAND. The laboratory is not responsible for the information provided by the customer which can affect the validity of the results, for example: sampling information such as date/time, field data etc.

Eurofins may subcontract the performance of part or all of the Services to a third party and the Customer authorises the release of all information necessary to the third party for the provision of the Services.

All samples become the property of Eurofins to the extent necessary for the performance of the Services.

Eurofins will not be required to store samples and may destroy or otherwise dispose of the samples or return the samples to the Customer (at the Customer's cost in all respects) immediately following analysis of the samples.

If the Customer pays for storage of the samples Eurofins will take commercially reasonable steps to store the samples for the agreed period in terms of industry practice. The Eurofins water sampling services uses IANZ approved methodology based on AS/NZS 5667 and / or best practice to collect and transport samples that are fit for the purpose of analytical testing. The laboratory is not responsible for sampling activities unless explicitly indicated by the statement "Sampled by Eurofins" on the report for water samples.

The Customer acknowledges that the Services are provided using the current state of technology and methods developed and generally applied by Eurofins and involve analysis, interpretations, consulting work and conclusions. Eurofins shall use commercially reasonable degree of care in providing the Services.

This report is produced and issued on the basis of information, documents and/or samples provided by, or on behalf of, the Customer and solely for the benefit of the Customer who is responsible for acting as it sees fit on the basis of this report. Neither Eurofins nor any of its officers, employees, agents or subcontractors shall be liable to the Customer nor any third party for any actions taken or not taken on the basis of this report nor for any incorrect results arising from unclear, erroneous, incomplete, misleading or false information provided to Eurofins.

Eurofins shall have no liability for any indirect or consequential loss including, without limitation, loss of production, loss of contracts, loss of profits, loss of business or costs incurred from business interruption, loss of opportunity, loss of goodwill or damage to reputation and cost of product recall (including any losses suffered as a result of distribution of the Customer's products subject of the Services prior to the report being released by Eurofins). It shall further have no liability for any loss, damage or expenses arising from the claims of any third party (including, without limitation, product liability claims) that may be incurred by the Customer. Eurofins General Terms and Conditions apply.

, eased under END OF REPORT

**Eurofins ELS Limited** 85 Port Road Seaview Lower Hutt Wellington 5010 NEW ZEALAND

+64 4 576 5016 Phone www.eurofins.co.nz



